Bakers Island Decr 28-1818

Sir

Agreable to your order I have had the Lantern
fitted with Double glass, and I do believe
the Mecanical part is as well Done as it is
Posable, yett Sir the glass is much fured
up with ice this Last Cold weather, so as to
hurt the Light (I believe much)

It is Believed the Dam Breach Now arises
from the Coarse Stone Work Between the
two Towers and A Passage of that about
A foot high with Cann be Done and made
perfectly tight, is thought by Mr Chase
and others will Remedy the evil

Your Hble Servt

Jos Cushing

Keeper Bakers Island
Light Dec^r 28 1818

Hon^ble D. L. Dearborn Esq^r.
Superintendent
Light Houses State Massachusetts
Boston
Care of Mr Potter