TREASURY DEPARTMENT
U. S. COAST GUARD
CGD1-FL 19c (Rev. 3-59)

RCS-O-217

GD1/A23

From: CDR D. W. WOODS (Inspecting Officer), Staff

To: Commander, First Coast Guard District (dcs)

Subj: BOON ISLAND LIGHT STATION; Staff Inspection of

Ref: (a) DISTRICT OPERATIONS INSTRUCTION NO. 18-56

1. Subject unit was inspected on 21 June 1961. (The following abbreviations are used herein to report conditions found during the inspection.)

VG - Very good
G - Good
F - Fair
P - Poor
U - Unsatisfactory

NB - Not observed
NC - Not corrected to date
NA - Not applicable
OB - On board and acceptable
NOB - Not on board; should be procured

2. Overall result of the inspection is classified as UNSAT.

3. Information and specific results of the inspection are as follows:

a. Complement:

(1) Authorized 4 (Military) [redacted]

(2) Assigned 4 (Military) [redacted]

(3) OinC LOCKHART, W.R. (name) BM2 (rate) (Acting)

(4) Remarks:

JUL 28 ENT'D
RPC

b. Administration:

(1)	Letter designating OinC in files (CG-222, Sec. 29-1-5B.)	OB
(2)	Personnel Allowance Sheet in files (CGHQ-9750)	NOB
(3)	Medical Allowance Sheet in files	OB
(4)	Keeping of station log and its disposal (GAI 15-58)	P
(5)	Directives (CG-236)	OB
(6)	Correspondence (CG-199)	OB
(7)	Record of Plant Property (CG-264-Volume 7)	OB
(8)	Paint and Color Manual (CG-263)	NC
(9)	Aids to Navigation Manual (CG-222)	OB
(10)	Local List of Lights (CG-158)	OB
(11)	File of Local Notice to Mariners	P
(12)	Machinery Instruction Manuals (As applicable)	
(13)	Annex "ROMEO" to CGDONE OP-PLAN	OB
(14)	Appendix I to Annex "ROMEO" to CGDONE OP-PLAN	OB

Further comments by inspecting officers (continued):

(c) Station walks are wood and are springy and rotten. Cement walks should be installed around light tower, around dwellings, and to heliport. CSMP card has been submitted.

(d) The dwelling should have a bathroom. There are no facilities for bathing and there is only a chemical toilet in generator building. CSMP card has been submitted.

(e) The unused dwelling is stone up to the second floor and appears to be structurally sound. Long range plans should include renovation of this building, construction of a new equipment building and razing all other buildings except the boat shed.

(f) Paint has flaked in areas on inside of light tower apparently due to a chemical reaction.

(g) Instructions have been issued that no more than one man go ashore at a time until maintenance is improved.