RH

58

Department of Commerce and Labor

1 inclos. LIGHT-HOUSE ESTABLISHMENT

Buffalo Breakwater
South Entrance, N.Y.
Repairs.

OFFICE OF ENGINEER, 10TH DISTRICT
BUFFALO, N. Y.

August 6, 1907.

The Light-House Board,

Washington, D.C.

The following repairs are needed at the Buffalo, N.Y., Breakwater South Entrance, south side, Light and Fog-Signal Station:

Light tower: Providing drainage to cellar

Pile Protection: New iron band for cluster of piles

Keepers' Dwelling: New oval glass in window

Fog-Signal House: New window shutter
Repairing corrugated iron roof

Repairing breakwater deck adjoining fog-signal house.

The total estimated cost to make the repairs is $370.93, as stated on Form 83, herewith.

It is recommended that the repairs be made by hired labor and the purchase of the necessary materials from the lowest responsible bidder, which is the most economical and advantageous method.

Authority is to-day asked to make the repairs

without the execution of a formal written contract, it being desired to do the work immediately.

Respectfully,

H.M. Adams

Colonel Corps of Engineers, U.S.A.
Engineer 10th L.H.District.