Sr

Boston Sept 30 1799

The Following is the State of the Boston Light House under my Care

Repairs for the Year 1800, pointing the Crack's in the N E Sid of the Light house and White Washing out Side

Sume Repairs on the Wharfes

Wanted at present 3 Large Squares of Glass in the Lanthorn 6 dittoo for Stare case windom 6 dittoo for the Dwelling house

Oil on Hand Sept 30	1015 Gallons
Wick yarn	47 Pound
Lamps in house	4
Old dittoo Kept as Reserve	4
Oil flasks	2
Boats	0

Thos Rice Superintendent

The Honrable

Benjamin Lincoln Esqr

Thd Ikner

The Honorable

Benjamin Lincoln Esq