

Treasury Department,
Fifth And^s Office,
July 21, 1849.

Sir, ^{ly} Having received the report of Mr. Miller, the general Inspector of Lights on the Lakes, as to the condition of the Lights his report in relation to those in your District is as follows:

^{ly} Buffalo Light.
This Light was found in the best possible condition - the conduct of the keeper good;

Cattaraugus Creek Light
Every thing here in good order - conduct of the keeper good.

Silver Creek Light
Nothing recommended to be done at present. Keepers conduct good.

Dunkirk Light & Beacon
Some repairs to Beacon necessary estimated cost 25 Dollars. A Boat is recom-
mended to cost 30 Dollars. L. H.

Nothing recommended to be done
at present. Keepers conduct good.

Quaker Light & Beacon
Some repairs to Beacon necessary
estimated cost 25 Dollars. A Boat is recom-
mended to cost 30 Dollars. Let the repairs
be made and the Boat supplied. Conduct
of Keeper good.

Parcelona Light.
The roof of the dwelling wants to be
reshingled, and a new eve trough, and
some small repairs in the interior of the
house, all estimated at 75 Dollars. Let
these repairs be made.

I have &c &c,
S. Pleasanton

Mr. Allen
Collector and Supt of Lts
Buffalo,
New York.